

SAFETY INSPECTION REPORT IN FAVOUR OF:

Name of Building: Army Goodwill School Bonyar
 Name of the Owner/Applicant: 161 1MP Boda Rampore.
 Address/Location of the Structure: Bonyar, near temple.
 Contact No. of Owner/Applicant and mail id: 01366252255.
 Year of Construction: Single story year 2001 & double story 2010
 Building Use with Name of Prominent Users: Schooling purpose.
 Purpose of issuance of Certificate: Upgradation with JK house.
 Name of Inspecting Engineer with Contact No. and e-mail: Lo. Arbaz Gekani (76) 789406157
Santhosh Kumar

VISUAL INSPECTION:

General Observations:

S.No	DESCRIPTION	REMARKS
1.	Type of Building	Four single stored & two double stored
2.	Age of Building	23 years & 15 years respectively
i)	As per Building Permission	
ii)	As per Electric Connection/Water Connection	Yes.
iii)	As per Affidavit by the Applicant.	Nel.
iv)	As per Physical Assessment by Inspecting Officer	
3.	No of wings	Nel.
4.	Mode of Use	
5.	No. of Stories	4 single stored & 2 double stored (long way).
6.	Architectural Plan Name of the Architect	Nel
7.	Structural Plan Name of the Consultant	Nel
8.	Building Plan Approval Date	Nel
9.	Occupation Certificate Date	Nel
10.	Last Repair Date	Nel
11.	Details of Repair.	Nel

* Age Proof supported by documents 2(i) or 2(ii) or 2(iii)

Signature of Inspecting
Junior Engineer

Assistant Engineer
Signature of Inspecting
Assistant Executive Engineer
Bonyar

Principal
Army Goodwill School
Bonyar

Structural Observations:

S.No	DESCRIPTION	LOCATION OF COMPONENT	GRADE	REMARKS
	FOUNDATION			
	Foundation Settlement/Timber Rot	N/A		
	Floor Settlement	N/A		
	Foundation exposed to aggressive environment like water logging dampness etc.	N/A		
A	SETTLEMENT/TILT DEFROMATION			
1.	Column	N/A		
2.	Walls	N/A		
B	CRACKS			
1.	Column	N/A		
2.	Beams	N/A		
3.	Slab	N/A		
4.	Plaster	N/A		
5.	External wall			Minor Cracks observed
6.	Internal wall	N/A		
C	CORROSION OF STEEL			
1.	Column	N/A		
2.	Beam	N/A		
3.	Slab	N/A		
D	LEAKAGES AND DAMPNES AND WATER PROOFING			
1.	External wall	N/A		
2.	Toilet	N/A		
3.	Terrace	N/A		
4.	Top floor slab	N/A		
5.	Inspection of overhead water tank	Yes.		
6.	Inspection of underground water tank	N/A		
7.	Leakages & damages plumbing lines/waterlines, drainage lines	N/A		

Signature of Inspecting
Junior Engineer

Signature of Inspecting
Assistant Executive Engineer

Signature of Inspecting
Assistant Executive Engineer

2 Toilet

FIRE SAFETY			
Fire gap on each side i.e. North, South, East and West.		To be reported by Concerned Fire and Emergency Services Department	
Number of Exits			
Sufficient width of Stair Case for safe exit of inhabitants			
Provision of ramps (if any)			
Status of Heavy Suspended Fixtures			
Such as Heavy false Ceilings etc.		Satisfactory	
E	DEFLECTION		
1.	Beam	Nil	
2.	Slab	Nil	
3.	Overloading on slab	Nil	
4.	Cantilever deflection	Nil.	
F	CONDITION OF OTHER COMPONENTS		
1	Staircase	Satisfactory	
2.	Balcony		
3.	Flooring		
4.	Ducts		
5.	Terrace		
6.	Plumbing System		
7.	Electric Supply Line		
8.	Water Supply Line		

* The report regarding defects to be duly supported by photographs which shall also include photographs of structure from all four sides.

Payment of Rs 2000/- has been received vide G.R No. _____ Dated: _____

Comments/Notations:

Nil	

Signature of Inspecting
Junior Engineer

Signature of Inspecting
Assistant Executive Engineer

Municipal
Arm Goodwill School
Bantwar